

ILC-x00 Troubleshooter

Ref #	Category of Problem	MANUAL PROCEDURE The technician performs these operations in sequence. Follow the arrows	RESULT Look for these results, if OK, take next step. If faulty, see Col. 3 & 4	SYMPTOMS OR CAUSES OF TROUBLE This column lists probable symptoms or causes of trouble	REMEDY Many problems can be overcome by checking these items
1000	Power Issues				
1010		Plug in DC power into ILC-x00 controller	Observe >>>	Does on-board LED illuminate either solid Yellow or solid Green? If neither color illuminates.	Check power supply, check polarity. Verify DC voltage generated by power supply is seen on ILC-x00 power connector If you can see the ILC-x00 unit through web Pilot, within the CS-BUS tab select the applicable ILC-x00 and right mouse click on the unit and hit Identify. This could clean the cache and enable the indicator lights to re-illuminate. Remove all load device connections from the ILC-x00 controllers and reboot to see if LEDs re-illuminate.
1020				No power to unit or faulty unit Unit may be internally hung due to an ESD glitch that only impacts these LEDs. A short on the Load (output) side would be impacting the status of these LEDs	
1030					
1100	Output color problems				
1110		Monochrome, RGB, RGBW and bi-white LEDs have been connected initially to a compatible ILC-x00 controller.		LEDs fail to light Wrong colors appear (i.e. Red, turns on Green, or Blue turns on Green, etc.) Multiple colors light when only one color is triggered LEDs appear faint or Green and Blue LEDs do not turn on at all	Check to see if the marked output on the ILC-x00 controller is routing to the same color on the LED strip. Remember "C" on the FLA strip is common positive. Also verify if the ILC-x00 is powered on. By default when an ILC-x00 is powered on all LEDs are triggered on (unless changed in software within Pilot). See above Typically, when in field soldering is performed whiskers of solder may short two adjacent lines (i.e. with RGB Blue might be shorted to Red, or Red to Green or in addition with RGBW, Green might be shorted to White) Improper power may be supplied. Typically, this is seen when a 12v power supply is driving 24v LEDs
1120				Miswiring, no input connection made, ILC-x00 not powered Miswiring of outputs from ILC-x00 controller to applicable input wires on FLA lighting strips	
1130				Typically, when in field soldering is performed whiskers of solder may short two adjacent lines (i.e. with RGB Blue might be shorted to Red, or Red to Green or in addition with RGBW, Green might be shorted to White) Improper power may be supplied. Typically, this is seen when a 12v power supply is driving 24v LEDs	Visually inspect your soldering work to make sure no whiskers are present. If found clean up solder joints. Check power supply to make sure its output matches the LEDs that are connected to the ILC-x00 controller
1140					Open Pilot and expand the "+" in front of the target ILC-x00 controller. Within the Properties window find the STARTUP entry which is marked 5.13.24. The reference in the third octet (a "24" refers to a default setting to turn on LEDs to that which is stored in Storage location 24 (i.e. which can be seen through selecting a RECALL 24). You can change the value for Recall 24 to any color or level you desire. Alternatively, if you wish to use Recall 24 for some other purpose, simply change the reference from "24" to some other number that has the color or brightness level that you desire for the power-up startup condition.
1150				When ILC-x00 controller is initially powered on, the connected LEDs turn on to full brightness and to White. Some installations may desire alternative colors or no illumination at all.	
1200	e-Node/ILC-x00 Communication Issues				
1210		Plug in CS-Bus cable from e-Node to one or more ILC-x00 controllers	Observe >>>	No ability to discover Device (ILC-x00) within Pilot Devices initially discovered from within Pilot may disappear from the discovery window	Substitute known good CS-Bus cable. Check pin outs on CS-Bus cable - correct pairs should be on 1, 2, 3, 4 & 5/6. Wiring should be 1-1, 2-2, 3-3, 4-4, 5-5, 6-6 Disconnect all ILC-x00 devices from the CS-Bus (or power off their unit by removing the power cord) and start adding one unit at a time and discovering with the Pilot application until unpredictable results are observed. Test that unit at minimum before proceeding.
1220				When devices are discovered, additional devices may inherit UID number from prior discovered units	Check wiring of CS-Bus, make sure ground is provided to negative terminal on ILC-100 and to Ground terminal on ILC-100m and ILC-400. If problem persists, update firmware to latest version available on website
1230				Data corruption on CS-Bus which may have resulted from miswiring, not grounding, negative input terminal on ILC-x00 controller or older firmware versions	
1240				The CS-BUS is a modified RS485 type communication bus. Sometimes when there are external electrical interferences, poor crimps or other factors present which might be causing sporadic bus communication problems, it is advised to provide an EOL termination	Wire a 120ohm resistor to pins 3 and 4 on the very end of the CS-Bus typically at the opposite end of the e-node where the e-Node is at the very beginning of the CS-Bus
1300	Bus/Communication Responsive Issues				
1310		Integration with a third-party automation or lighting systems has been accomplished but keypad or dimmer/slider seems to operate slowly or sporadically	Observe >>>	When a slider or button is pressed for a single unit, control is responsive When a slider or button is pressed in quick succession to control many units including real time changes or some RGB-type color pickers are being used with some automation environments and their use appears sluggish or stuttering like Actions evoked from the Pilot Virtual keypad or third-party automation systems may sometimes work and then other times be delayed	Typically if many units are all being controlled through macros and lots of back channel information is being provided/processed, it might be a good idea to either (i) reduce the backchannel information by just reporting #RGB or RGB data but not both or (ii) turn off NOTIFY where not needed. Change this from within Pilot (see section on Notify).
1320				No problem here. Most likely any backchannel feedback (see NOTIFY section) is not overwhelming other bus traffic and automation system can process all backchannel information in real time.	See the e-Node/ILC-x00 Communication section above
1330				The Notify parameter which either provides Hue/Saturation/Brightness feedback or Red/Green/Blue or RGBW feedback may be enabling a plethora of data onto some buses which might be overwhelming some automation systems. Communication issues rather than bus traffic issues might be the problem.	
1400	Firmware Upgrade Issues				
1410		Determine UID of target device using Pilot application. Close down Pilot, then launch firmware executable and enter UID of target controller and follow directions	Observe >>>	Does Firmware Update Notification show success if not	Pilot application may still be open-close application UID entered in updater may be incorrect. Open Pilot and observe correct UID and once again close Pilot and try updater
1500	Addressing Issues				
1510		From the factory, each ILC-x00 controller comes with a default factory address of 2.1.D (Zone of 2, Group of 1 and a non-set Node of 0). In order to individually address a unit, it must have a non-zero Node address which needs to be field programmed	Observe >>>	If a unit is left with a Node address of "0" (i.e. Z/N/N of 2.1.0), then that controller can only be controlled part of a general group (i.e. Z/N/N address of 2.1.0) rather than individually. Also, no backchannel information will be available even if NOTIFY is turned ON (see Notify/Back Channel Issues) for units left with a Node address of "0" Without programming each controller separately with Pilot, no individual control is possible	Open the Pilot application and expand the ILC-x00 controller that you wish to program by selecting the "+" mark, then select the BUS tab and enter your Z/N/N address making sure that you do not enter a "0" for any field
1520		Multiple ILC-x00 controllers are operating in unison and need to be programmed to operate separately	Observe >>>	The actual ILC-x00 controller being targeted through a command is not being controlled	See above instruction
1530		A Zone/Group/Node address exceeding 254 for any field has been entered	Observe >>>	Zone/Group/Node addresses must fall in the range 1 to 254 for each octet	Change the address for any targeted controller to a number between 1 and 254
1600	Notify/Back Channel Issues				
1610		The parameter NOTIFY must be programmed to enable back channel information.	Observe >>>	Before programming, backchannel information with "Y" in front of some does not appear (i.e. 12.1.1.1 LED WALL/ILC-240, 240 or similar does not appear) Backchannel for specific controller does not appear, although backchannel occurs for some devices	Open Pilot application and hit discover e-nodes and then discover Devices within the View Map window. Expand the Devices and look under the LED tab for NOTIFY and turn to appropriate setting. ("Color" for RGB feedback, "Value" for old-school RGB feedback, and BOTH for both)
1620				Notify needs to be turned on for ILC-x00 device or for each channel Specific backchannel information is generated for all devices with non-zero Zone/Group/Node addresses (Z/N)	Make sure the device from which you are wishing to receive backchannel information has a non-zero Z/N address assigned. If not, assign it using directions above
1630				With earlier versions of ILC-x00 firmware, a query of a wildcard address (2.1.0) only provided backchannel notification from the "speaker of the class" which had a Node address of "1" (within the same Z/N series). That information was reported back from that speaker's Node address (i.e. 2.1.1) rather than from the wildcard address (i.e. 2.1.0).	Updates the firmware on any ILC-x00 controller where you desire this level of functionality. Consult Firmware Revision Notes on the ConvergingSystems.com website to determine if your firmware is impacted here. (see link at the bottom of this troubleshooter).
1700	Chabing from ILC-x00 controller to load (LEDs) is becoming hot or burning up				
1710		You have wired your ILC-x00 without consulting the Voltage Drop Table available from Converging Systems	Observe >>>	LEDs are dim, or the wire run between the ILC-x00 controller and the LEDs are becoming very hot or have burned Insufficient wire gauge to support connected LEDs	Review Voltage Drop Tables as applicable for your particular LEDs to be driven from the ConvergingSystems.com website. Make sure that proper wire gauge is being used depending upon (i) the load that will be driven and (ii) the distance of the wire from the ILC-x00 controller and the beginning of the FLA or similar lighting device
1800	Problems not identified above or for more troubleshooting				
1810		Perform a Factory Reset Note: specific programming of unit may be lost in the process	Observe >>>	Unit is brought back to factory settings based on the current version of firmware programmed	
1820				Programming issues, bad communication issues, misc. issues If ILC-400 in RGBW mode If ILC-400 in 4 channel mode	For ILC-400 RGBW mode remove shroud to left of 2-pin power plug and depress slider button and hold until three sets of flashes are observed, then release button For ILC-400 RGBW mode remove shroud to left of 2-pin power plug and depress slider button and hold until two sets of flashes are observed, then release button
1830				If ILC-100c	For ILC-100c use paperclip and carefully insert into vertical side wall to find internal reset button. Hold down reset button until three sets of flashes are observed, then release button
1840				If ILC-100m	For ILC-100m use paperclip and vertically on edge of PCB where it is blank DISC and gently press inwards to find Discovery Button (not downwards) and depress tiny reset button until three sets of flashes are observed, then release button
1850					
3000	Other Information				
3010		Consult Firmware Release Notes	Determine platform >>>		http://www.convergingystems.com/software/ILC400/release_notes&... If ILC-400
3020					Consult ILC-400 for general release notes which may apply. Go to http://www.convergingystems.com/downloads_library.php and click on ILC-100c controller to see if WIP release notes are present If ILC-100c
3030					Consult ILC-400 for general release notes which may apply. Go to http://www.convergingystems.com/downloads_library.php and click on ILC-100m controller to see if WIP release notes are present If ILC-100m